CORRES CONTROL INCOMING LTR NO 2766 RF93 DUE DATE **ACTION** DIST. BENEDETTI, R L BENJAMIN, A BERMAN, H S CARNIVAL, G.J COPP, R D CORDOVA, R C DAVIS, J G FERRERA, DW HANNI, B J HEALY TJ HEDAHL TG KIRBY WA KUESTER AW LEE E M MANN HE VIARX GE MCKENNA F G VIORGAN R V PIZZUTO V M POTTER GL RILEY JH SANDLIN NB SATTERWHITE DG SCHUBERT A L SETLOCK G H SHEPLER R L SULLIVAN MT SWANSON, ER WILKINSON RB

WILSON J M

Primrose

Bisby

ZANE JO



Department of Energy

ROCKY FLATS OFFICE P O BOX 928 GOLDEN COLORADO 80402-0928

JUN 1 6 1993

93-DOE-06765

Mr Martin Hestmark U S Environmental Protection Agency, Region VIII ATTN Rocky Flats Project Manager, 8HWM-RI 999 18th Street, Suite 500, 8WM-Č Denver, Colorado 80202-2405

Mr Gary Baughman Hazardous Waste Facilities Unit Leader Colorado Department of Health 4300 Cherry Creek Drive South Denver, Colorado 80222-1530

Gentlemen

There has been a change to the proposed final Operable Unit 2 (903 Pad, Mound, East Trenches) Technical Memorandum (TM) 8, the revised Bedrock Work Plan The proposed final TM 8, submitted for your approval May 21, 1993, (93-DOE-05210), states that EPA method 8010 would be used for the quick turnaround analytical sampling. The contractor analytical laboratory would prefer to use EPA method 8260 The detection limits for both methods are similar We believe that the alternate method 8260 meets the requirements for the quick turnaround analytical samples Your staffs were notified of this change at the May 26, 1993, meeting and follow-up phone conversations on May 28, 1993

Approval of the final TM 8 would include approval of the use of EPA method 8260 If you have any questions, please contact Scott Grace of my staff at (303) 966-7199

Sincerely,

	James K. Hariman
CORRES CONTROL x x	Assistant Manager for Transition
35711123 357777	(and Environmental Management

Reviewed for Addressee Corres Control RFP

A Rampertaap, EM-453 Primrose, EG&G

0-4	٠	4-	44	

⊰F 46522 (Rev 3/93)

Fraser, EPA Schieffelin, CDH

ΔΠ	MAIR	U D	En	ORD
MU	IVIII	71 V	LL	UKD